



$$\begin{aligned} 2.35 & \times 1.85 = 4.3475 \\ 2.40 & \times 1.85 = 4.44 \\ 2.75 (2.30 + 2.80) & = 10.45 \\ 2.25 & \times 2.45 = 5.5125 \\ 113.555 & \\ 54.27 & \end{aligned}$$

$$\begin{aligned} 11.50 (6.75 + 4.30) & = 127.075 \\ 8.85 & \times 2.15 = 19.0275 \\ 2.25 & \times 1.90 = 4.275 \\ 10.95 & \times 0.25 = 2.7375 \\ 159.775 & \\ 80.82 & \end{aligned}$$

$$\begin{aligned} 2.55 & \times 2.85 = 7.3575 \\ 18.75 (4.40 + 3.15) & = 149.1125 \\ 10.70 & \times 5.30 = 56.71 \\ 27.30 (5.70 + 1.10) & = 188.800 \\ 20.95 & \times 10.30 = 215.785 \\ 15.15 & \times 2.65 = 40.1475 \\ 13.85 (6.75 + 4.65) & = 144.875 \\ 2.80 & \times 2.30 = 6.44 \\ 9.50 & \times 3.00 = 28.500 \\ 12.65 & \times 2.75 = 34.7875 \\ 1206.290 & \\ 603.14 & \end{aligned}$$